

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,974,172 B2
DATED : December 13, 2005
INVENTOR(S) : Gebreselassie et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1.

Line 1, should read -- VEHICLE COCKPIT ASSEMBLIES HAVING --.

Column 12.

Line 6, should read -- through assembly first side via the substrate opening, and --.

Line 35, should read -- a dash insulator that is configured to be attached to a --.


Column 13.

Line 5, should read -- cylinder assembly via an aperture in the pass-through assem- --.

Line 38, should read -- a dash insulator that is configured to be attached to the --.

Signed and Sealed this

Twenty-fifth Day of April, 2006



JON W. DUDAS
Director of the United States Patent and Trademark Office